

## EATON 2023 ASPHALT PATCHING

LOCATION	L	W	SF	L	W	SF	L	W	SF	TLT. SY
Patch and concrete collar 180 Cherry	20	3	60			0			0	6.67
Patch 225 Juniper	72	5	360			0			0	40.00
Patch 3rd ST and Cedar	30	3	90			0			0	10.00
Patch 90 Juniper	15	10	150	10	5	50			0	22.22
Patch Maple 9in front of library	15	10	150	20	15	300			0	50.00
Patch First and Juniper	25	15	375			0			0	41.67
Patch 3rd and Cherry	35	5	175			0			0	19.44
Patch South Maple and Collins ST	20	15	300			0			0	33.33
Patch Orchard and Buckeye Ave	5	5	25	5	5	25			0	5.56
Patch South Elm and Bluegrass	30	3	90	5	5	25			0	12.78
Patch Hickory and East 3rd ST	15	15	225			0			0	25.00
Patch Collins ST and Cherry	25	25	625			0			0	69.44
Patch East 3rd ST and Hickory	50	3	150			0			0	16.67
Patch East 4th ST and Hickory	10	5	50			0			0	5.56
Patch East 4th ST and Laurel	30	3	90	30	3	90			0	20.00
Patch East 4th ST and Chestnut	30	3	90			0			0	10.00
Patch 1440-1450 Hawkridge RD	15	15	225	15	15	225	20	20	400	94.44
Patch Hawkstone DR near swimming pool	5	5	25			0			0	2.78
Patch Parkridge entrance	30	5	150	40	3	120			0	30.00
Patch gutter pan North of Park	30	5	150	30	5	150			0	33.33
Patch Eagle DR gutter pan South of park	30	10	300	40	5	200			0	55.56
Patch Kestrel RD gutter pan	40	3	120	30	3	90			0	23.33
Patch Grayhawk RD intersection	30	10	300	60	3	180			0	53.33
Patch Cooper Hawk RD near gutter pan	30	15	450			0				50.00